

**TRACY MUNICIPAL AIRPORT
PAVEMENT EVALUATION STUDY
PAVEMENT MAINTENANCE/MANAGEMENT PLAN**

**Appendix A
Geotechnical Data**


A series of soil (geotechnical) studies were conducted by the office of Reinard W. Brandley, Consulting Airport Engineer in the past as well as in 2012 for the pavement evaluation study for the Tracy Municipal Airport. These studies consisted of drilling a series of exploratory test holes and test pits, obtaining undisturbed soil samples and bulk soil samples from these test holes and test pits, and conducting a series of laboratory tests on the samples obtained. The data obtained from these test borings and test pits have been used in this Pavement Evaluation Study. The results of these studies have been summarized in this Appendix, as follows:

Plates


Plate No. A1	Soil Test Hole Location Map
Plate No. A2	1975 Soil Profiles (U1A – U10A)
Plate No. A3	1975 Soil Profiles (U11A – U19A)
Plate No. A4	1983 Soil Profiles (U1B – U6B)
Plate No. A5	1985 Soil Profiles (U7C – U12C)
Plate No. A6	1989 Soil Profiles (TP 1D – TP 8D)
Plate No. A7	2012 Soil Profiles (U1E – U12E)

Tables

Table No. A1	Summary of Geotechnical Testing – Native Soils
Table No. A2	Grading Analysis – Aggregate Base Course (1975)



- LEGEND:**
- ◆ SS IIA 1975 SOIL SACK SAMPLES
 - ◆ U3A 1975 SOIL BORINGS - (U1A - U19A)
 - ◆ U4C 1983 SOIL BORINGS - (U1B - U6B)
 - ◆ U8C 1985 SOIL BORINGS - (U7C - U12C)
 - TP 6D 1989 SOIL TEST PITS - (TP 1D - TP 8D)
 - ⊙ U5E 2012 SOIL BORINGS - (U1E - U12E)



VERIFY SCALES.
 BAR IS ONE INCH ON ORIGINAL DRAWING.
 IF NOT ONE INCH ON THIS SHEET, ADJUST SCALES ACCORDINGLY.





Reinard W. Brandley
 CONSULTING AIRPORT ENGINEER
 8125 King Road, Suite 201 • Lodi, California 95690-8004 • (916) 692-4725







NO.	REVISIONS	BY	DATE	ENGINEER OF RECORD

TRACY MUNICIPAL AIRPORT
 TRACY, CALIFORNIA
PAVEMENT EVALUATION
 SOIL TEST HOLE LOCATION MAP


DESIGN BY: DB
 DRAWN BY: DB
 CHKD BY: RWB
 DATE: MARCH 11, 2013
 CONTRACT NO.: -
 PROJECT NO: 51.04-13
 DWG FILE: -
 DRAWING SCALE: 1"=200'
 SHEET NUMBER
 PLATE No. A1




NO.	REVISIONS	BY	DATE	REASON	DATE	TRACED	DATE	CHECKED	DATE
COUNTY OF SAN JOAQUIN STATE OF CALIFORNIA		DATE		DATE		DRAWING NO.		SCALE	
TRACY MUNICIPAL AIRPORT TRACY, CALIFORNIA		51.04.2		51.04 A2-3		1" = 50 BLOWS VERT. 1" = 5'		REGISTERED CE 8044	
REINARD W. BRANDLEY CONSULTING CIVIL ENGINEER HOME AVENUE PROFESSIONAL CENTER TELEPHONE 922-4725 801 HOME AVENUE SACRAMENTO, CALIFORNIA 95825									
DATE SEPT. 3, 1975									
SHEET NUMBER					12 OF SHEETS				



NO.	REVISIONS	BY	DATE	APPROVED	DATE	TRACED	DATE	DATE	
COUNTY OF SAN JOAQUIN STATE OF CALIFORNIA		DATE		DATE		DATE		DATE	
TRACY MUNICIPAL AIRPORT TRACY, CALIFORNIA		DRAWING NO.		5104 A2-2		CONTRACT NO.		5104 A2	
SOIL PROFILE SHEET NO. 1		REGISTERED		CE. 8044		SCALE		1" = 5' HORIZONTAL 1" = 5' VERTICAL	
REINARD W. BRANDLEY CONSULTING CIVIL ENGINEER HOME AVENUE PROFESSIONAL CENTER TELEPHONE 922-4725 681 HOME AVENUE SACRAMENTO, CALIFORNIA 95825		DATE		SEPT. 3, 1975		SHEET		NUMBER	
						11 OF		SHEETS	



SOIL PROFILE LEGEND



NOTE:
DATE OF ALL BORINGS 4-14-83


IT IS UNDERSTOOD AND AGREED THAT THIS SUBSURFACE INFORMATION WAS OBTAINED AND WAS INTENDED FOR OWNER'S DESIGN AND ESTIMATING PURPOSES ONLY. IT IS FURTHER UNDERSTOOD AND AGREED THAT EACH BIDDER IS SOLELY RESPONSIBLE FOR ALL ASSUMPTIONS, DEDUCTIONS OR CONCLUSIONS WHICH MAY BE MADE OR OBTAINED FROM EXAMINATION OF THE BORING LOGS AND OTHER RECORDS OF SUBSURFACE INVESTIGATIONS AND TESTS THAT ARE FURNISHED BY THE OWNER.




GRAPHIC SCALES

NO.	REVISIONS	BY	DATE	DESIGNED	DATE	TRACED	DATE	CHECKED	DATE
COUNTY OF SAN JOAQUIN STATE OF CALIFORNIA		TRACY MUNICIPAL AIRPORT TRACY, CALIFORNIA		DRAWN P.V.K.		CONTRACT NO. 5106A		DRAWING NO. 5106A	
		SOIL PROFILE SHEET No 1		REGISTERED C.E. 8044		SCALE AS SHOWN			
COUNTY OF SAN JOAQUIN STATE OF CALIFORNIA TRACY MUNICIPAL AIRPORT TRACY, CALIFORNIA SOIL PROFILE SHEET No 1 1983 SOIL BORINGS - (U1B - U6B)									
3044 Hillcrest Drive Sacramento, California 95828 Richard W. Trandley CONSULTING GEOTECHNICAL ENGINEER 22-4728									
DATE 4/15/83									
SHEET NUMBER 20 OF 20 SHEETS									


VERIFY SCALES.
 BAR IS ONE INCH ON ORIGINAL DRAWING.
 0" = 1"
 IF NOT ONE INCH ON THIS SHEET, ADJUST SCALES ACCORDINGLY.



1989 SOIL TEST PITS



1989 SOIL TEST PITS



REVISIONS

NO.	DATE	BY	DESCRIPTION

TRACY MUNICIPAL AIRPORT
 CALIFORNIA
PAVEMENT EVALUATION
 1989 SOIL PROFILES (TP 1D - TP 8D)


DESIGN BY: DB
 DRAWN BY: DB
 CHKD BY: RWB
 DATE: MARCH 11, 2013
 CONTRACT No. -
 PROJECT NO: 51.04-13
 DWG FILE: -
 DRAWING SCALE: AS SHOWN

SHEET NUMBER
 PLATE No. A6


Reinald W. Brandley
 CONSULTING AIRPORT ENGINEER
 License No. C 85338
 Exp. 6-30-2014
 6125 King Road, Suite 201
 Livermore, California 94550-8004
 (916) 682-4725

VERIFY SCALES
 BAR IS ONE INCH ON ORIGINAL DRAWING.
 0' = 1"
 IF NOT ONE INCH ON THIS SHEET, ADJUST SCALES ACCORDINGLY.


Reinard W. Brandley
 CONSULTING AIRPORT ENGINEER
 8125 King Road, Suite 201 • Lodi, California 95240-8004 • (916) 652-4725




2012 SOIL PROFILES - HANGAR AREA H4




2012 SOIL PROFILES - HANGAR AREA H3



2012 SOIL PROFILES - TAXIWAY C AND ROAD E



2012 SOIL PROFILES - NORTH APRON DEVELOPMENT



NO.	REVISIONS	BY	DATE	ENGINEER OF RECORD

TRACY MUNICIPAL AIRPORT
 CALIFORNIA
PAVEMENT EVALUATION
 2012 SOIL PROFILES (U1E - U12E)

DESIGN BY: DB
 DRAWN BY: DB
 CHKD BY: RWB
 DATE: MARCH 11, 2013
 CONTRACT NO. -
 PROJECT NO: 51.04-13
 DWG FILE: -
 DRAWING SCALE: AS SHOWN
 SHEET NUMBER
 PLATE No. A7

APPENDIX A
TABLE NO. A1

GEOTECHNICAL TESTING
REINARD W. BRANDLEY - CONSULTING AIRPORT ENGINEER
TRACY MUNICIPAL AIRPORT
TRACY, CALIFORNIA

PAVEMENT MANAGEMENT AND MAINTENANCE PLAN
SUMMARY OF GEOTECHNICAL TESTING - NATIVE SOILS

Date of Sample	Sample Identification	Depth Below Surface (ft.)	Soil Classification	Liquid Limit	Plasticity Index	Maximum Dry Density (pcf)	Optimum Moisture (%)	CBR @ 0.1" Penetration			Swell at 100% Compaction (%)
								100% Compaction (%)	95% Compaction (%)	90% Compaction (%)	
1975	SS IA	0	Brown Silty Clay	29	16	121.8	11.8	11	7	3.5	-
1975	SS IIA	0	Brown Silty Clay	32	16	126.5	10.6	8.3	6	4.8	-
1975	U1A	3	Brown Silty Clay	31	17	-	-	-	-	-	-
1975	U5A	3	Dark Brown Silty Clay	23	8	-	-	-	-	-	-
1975	U9A	3.5	Dark Brown Sandy Clay	30	14	-	-	-	-	-	-
1975	U11A	3	Dark Brown Sandy Clay	38	20	-	-	-	-	-	-
1975	U12A	3	Black Med. Plastic Clay (Gravelly)	27	12	-	-	-	-	-	-
1975	U14A	3	Dark Brown Med. Plastic Clay	29	16	-	-	-	-	-	-
1975	U14A	6.5	Brown Silty Clay	32	14	-	-	-	-	-	-
1975	U18A	3	Black Med. Plastic Clay (Gravelly)	31	16	-	-	-	-	-	-
1983	U1B	1.5	Dark Brown Sandy Silty Clay	33	12	-	-	-	-	-	-
1983	U2B	1.5	Dark Brown Sandy Clayey Silt	28	8	-	-	-	-	-	-
1983	U4B	1	Dark Brown Sandy Silty Clay	32	12	-	-	-	-	-	-
1983	U5B	2.2	Brown Sandy Silty Clay	31	11	-	-	-	-	-	-
1985	U7C	1.5	Brown Sandy Clay	28	8	-	-	-	-	-	-
1985	U8C	1	Brown Sandy Silt	34	12	-	-	-	-	-	-
1985	U9C	1	Brown Sandy Clay	32	11	-	-	-	-	-	-
1989	TP 3D	1	Brown Sandy Silty Clay	32	18	123.4	12	6	4.5	-	2.8
1989	TP 6D	1	Brown Sandy Silt	27	10	125	11.3	16	9.5	-	1.3
1989	TP 7D	1	Brown Sandy Silt (Clayey)	27	13	-	-	-	-	-	-
2012	U2E	2.5	Brown Silty Clay	31	15	-	-	-	-	-	-
2012	U11E	6.5	Brown Sandy Silt	26	5	-	-	-	-	-	-

**APPENDIX A
TABLE NO. A2**

**GEOTECHNICAL TESTING
REINARD W. BRANDLEY * CONSULTING AIRPORT ENGINEER**

**TRACY MUNICIPAL AIRPORT
TRACY, CALIFORNIA**

PAVEMENT MANAGEMENT AND MAINTENANCE PLAN

GRADING ANALYSIS - AGGREGATE BASE COURSE (1975)

Sieve Size	Sample	Grading Analysis (% Passing)			
		U2A	U7A	U8A	U12A
2"		-	100	-	100
1.5"		100	92	100	97
1"		95	84	95	90
3/4"		86	79	90	79
1/2"		74	60	80	66
3/8"		66	59	72	60
#4		49	35	53	43
#10		38	25	38	31
#20		30	18	28	24
#40		24	14	21	18
#80		16	9.1	13	12
#200		11	6.3	9	8.2
Sand Equivalent		28	35	29	25
Percent Crushed (1 face)		72	82	74	71

**TRACY MUNICIPAL AIRPORT
PAVEMENT EVALUATION STUDY
PAVEMENT MAINTENANCE/MANAGEMENT PLAN**

Appendix B

Falling Weight Deflectometer Test Data

Falling Weight Deflectometer (FWD) tests were conducted on all pavements on the airport. On each runway two rows of FWD tests were conducted, one on each side of the runway centerline, at a distance of approximately 10 feet from the centerline. These tests were located at a spacing of approximately 200 feet, which provided general longitudinal spacing of 100 feet between tests. FWD tests were also conducted on all taxiways and taxilanes at a distance of 10 feet from centerline and at longitudinal spacing of approximately 200 feet. On all aprons FWD tests were conducted on an approximate 100 by 100 foot grid. On all hangar taxilanes FWD tests were conducted in the wheel path of the taxilane at a spacing of approximately 100 feet.

The Falling Weight Deflectometer tests are generally conducted at two different loadings and the applied load is measured by load cells. As a result of variations in resistance, the applied load varies somewhat from the anticipated load. In order to provide comparable test results, all data were normalized to standard loads of 10, 14, and/or 17 kips.

The location of the test, starting point of the test, and location of Station 0+00 for each row of tests are shown on Plates B1 through B3. The FWD data for the center deflections under applied load are indicated on these drawings for each test location. The location of Station 0+00 at the start of each row of tests and the direction of test are reflected in the plots as Station 0+00 in Plates No. B4 through B38.

For each row of FWD tests on each segment of pavement a graph showing the center plate deflection at each station has been prepared and is shown on Plates B4 through B38. These data show the uniformity of strength as reflected by deflection of the pavement sections and identify the hard spots and the soft spots. For calculation purposes in order to back calculate Modulus of Elasticity, critical values of deflection for each fairly uniform section has been indicated by horizontal lines.

A camera was mounted on the FWD equipment and a photograph of the surface of the pavement was taken at the location of each FWD test. These photographs are useful historical documents since they show the condition of the existing pavement at the time and location of each FWD test. An electronic copy of these photographs are enclosed with this report

The results of these studies have been included in this Appendix, as follows:

**TRACY MUNICIPAL AIRPORT
PAVEMENT EVALUATION STUDY
PAVEMENT MAINTENANCE/MANAGEMENT PLAN**

Appendix B

Falling Weight Deflectometer Test Data

Plates

Plates No. B1-B3 Falling Weight Deflectometer Test Data Summary - Half Size
(A full size copy of Plates No. B1-B3 is included in the pocket in
the back cover of this report.)

Plates B4 through B38 – FWD Deflection Data Profiles

Plate No. B4	Runway 12-30
Plate No. B5	Taxiways B and E
Plate No. B6	Runway 8-26
Plate No. B5	Taxiways A and F
Plate No. B6	Taxiway D (North) – Aprons A1, A3, and A4
Plate No. B9	Taxiway D (South)
Plate No. B10	Taxiway C
Plate No. B11	Apron Row A1 – (Apron A2 and Hangar Area H2)
Plate No. B12	Apron Row A2 – (Apron A1 and A2)
Plate No. B13	Apron Row A3 – (Apron A2)
Plate No. B14	Apron Row A4 – (Apron A1 and A2)
Plate No. B15	Apron Row A5 – (Apron A1 and A2)
Plate No. B16	Apron Row A6 – (Apron A1 and A2)
Plate No. B17	Apron Row A7 – (Apron A2)
Plate No. B18	Apron Row A8 – (Apron A2)
Plate No. B19	Apron Row A9 – (Apron A1, A4 and A3)
Plate No. B20	Apron Row A10 – (Apron A1, A4 and A5)
Plate No. B21	North Hangar Row H1 – (Hangar Area H1)
Plate No. B22	North Hangar Row H2 – (Hangar Area H1)
Plate No. B23	North Hangar Row H3 – (Hangar Area H1)

**TRACY MUNICIPAL AIRPORT
PAVEMENT EVALUATION STUDY
PAVEMENT MAINTENANCE/MANAGEMENT PLAN**



Appendix B

Falling Weight Deflectometer Test Data

Plates (continued)

Plates B4 through B38 – FWD Deflection Data Profiles

Plate No. B24	North Hangar Row H4 – (Hangar Area H2)
Plate No. B25	North Hangar Row H5 – (Hangar Area H2)
Plate No. B26	North Hangar Row H6 – (Hangar Area H2)
Plate No. B27	North Hangar Row H7 – (Hangar Area H2)
Plate No. B28	North Hangar Row H8 – (Hangar Area H2)
Plate No. B29	Taxiway D (South) – (Hangar Area H3)
Plate No. B30	South Hangar Row B1 – (Hangar Area H3)
Plate No. B31	South Hangar Row B2 – (Hangar Area H3)
Plate No. B32	South Hangar Row B3 – (Hangar Area H4)
Plate No. B33	South Hangar Row B4 – (Hangar Area H3 and H4)
Plate No. B34	Road A – Airport Access Road
Plate No. B35	Road B – Airport Second Access Road
Plate No. B36	Road C – FBO Parking Lot
Plate No. B37	Road D – North Apron Access Road (Apron Row A6)
Plate No. B38	Road E – South Hangar Access Road (S. Hangar Row B5)



VERIFY SCALES
 BAR IS ONE INCH ON ORIGINAL DRAWING.
 IF NOT ONE INCH ON THIS SHEET, ADJUST SCALES ACCORDINGLY.

Reinard W. Brandley
 CONSULTING AIRPORT ENGINEER
 6125 King Road, Suite 201
 Livermore, California 94550-8604
 (916) 852-4725




NO.	REVISIONS	BY	DATE	ENGINEER OF RECORD

TRACY MUNICIPAL AIRPORT
 CALIFORNIA
PAVEMENT EVALUATION
 FALLING WEIGHT DEFLECTOMETER TEST DATA SUMMARY
 SHEET No. 1

DESIGN BY: DB
 DRAWN BY: DMB
 CHKD BY: RWB
 DATE: MARCH 18, 2013
 CONTRACT NO. -
 PROJECT NO: 51.04-13
 DWG FILE: -
 DRAWING SCALE: 1"=200'



SHEET NUMBER
 PLATE No. B1



NOTES:
 1. PAVEMENT TESTING & SURVEY PERFORMED OCTOBER 9, 2012

VERIFY SCALES.
 BAR IS ONE INCH ON ORIGINAL DRAWING.
 0 1"
 IF NOT ONE INCH ON THIS SHEET, ADJUST SCALES ACCORDINGLY.

NOTES:
 1. PAVEMENT TESTING & SURVEY PERFORMED OCTOBER 9, 2012




Reinald W. Brandley
 CONSULTING AIRPORT ENGINEER
 6125 King Road, Suite 201 • Loomis, California 95650-0824 • (916) 622-4725

NO.	REVISIONS	BY	DATE	ENGINEER OF RECORD

TRACY MUNICIPAL AIRPORT
 CALIFORNIA
PAVEMENT EVALUATION
 FALLING WEIGHT DEFLECTOMETER TEST DATA SUMMARY
 SHEET No. 2

DESIGN BY: DB
 DRAWN BY: DMB
 CHKD BY: RWB
 DATE: MARCH 18, 2013
 CONTRACT No. -
 PROJECT NO: 51.04-13
 DWG FILE: -
 DRAWING SCALE: 1"=60'
 SHEET NUMBER
 PLATE No. B2



VERIFY SCALES
 BAR IS ONE INCH ON ORIGINAL DRAWING.
 IF NOT ONE INCH ON THIS SHEET, ADJUST SCALES ACCORDINGLY.



LEGEND
 X 10 <14>(17)
 ——— CENTER OF PLATE DEFLECTION @ 17K LOAD
 ——— CENTER OF PLATE DEFLECTION @ 14K LOAD
 ——— CENTER OF PLATE DEFLECTION @ 10K LOAD
 ↑ DATA BEGINNING STATION
 ——— EXISTING EDGE OF PAVEMENT
 - - - EXISTING FENCE
 ▨ EXISTING BUILDING

NOTES:
 1. PAVEMENT TESTING & SURVEY PERFORMED OCTOBER 9, 2012

Reinard W. Brandley
 CONSULTING AIRPORT ENGINEER
 License No. 55555-0004
 License, California 55555-0004
 6125 King Road, Suite 201
 (916) 852-4725




NO.	REVISIONS	BY	DATE	ENGINEER OF RECORD


TRACY MUNICIPAL AIRPORT
 CALIFORNIA
PAVEMENT EVALUATION
 FALLING WEIGHT DEFLECTOMETER TEST DATA SUMMARY
 SHEET No. 3

DESIGN BY: DB
 DRAWN BY: DMB
 CHKD BY: RWB
 DATE: MARCH 18, 2013
 CONTRACT No. -
 PROJECT NO: 51.04-13
 DWG FILE: -
 DRAWING SCALE: 1"=60'
 SHEET NUMBER
 PLATE No. B3


Tracy Municipal Airport - FWD Deflection Data
 Runway 12-30
 (Station 0+00 at R/W 30 End)




Tracy Municipal Airport - FWD Deflection Data
 Taxiways B and E
 (Station 0+00 at RW 30)




Tracy Municipal Airport - FWD Deflection Data
 Runway 8-26
 (Station 0+00 at RW 26 End)




Tracy Municipal Airport - FWD Deflection Data
 Taxiways A and F
 (Station 0+00 at RW 26)




Tracy Municipal Airport - FWD Deflection Data
 Taxiway D (North), Aprons A1, A3, A4
 (Station 0+00 at RW 12-30)




Tracy Municipal Airport - FWD Deflection Data
 Taxiway D (South)
 (Station 0+00 at RW 12-30)




Tracy Municipal Airport - FWD Deflection Data
 Taxiway C
 (Station 0+00 at RW 12-30)




Tracy Municipal Airport - FWD Deflection Data
 Apron Row A1 - (Apron A2 and Hangar Area H2)
 (Station 0+00 at T/W B)




Tracy Municipal Airport - FWD Deflection Data
 Apron Row A2 - (Apron A1 and A2)
 (Station 0+00 at North-West Edge)




Tracy Municipal Airport - FWD Deflection Data
 Apron Row A3 - (Apron A2)
 (Station 0+00 at West Edge)




Tracy Municipal Airport - FWD Deflection Data
 Apron Row A4 - (Apron A1 and A2)
 (Station 0+00 at West Edge)




Tracy Municipal Airport - FWD Deflection Data
 Apron Row A5 - (Apron A1 and A2)
 (Station 0+00 at T/W D North)




Tracy Municipal Airport - FWD Deflection Data
 Apron Row A6 - (Apron A1 and A2)
 (Station 0+00 at T/W D North)




Tracy Municipal Airport - FWD Deflection Data
 Apron Row A7 - (Apron A2)
 (Station 0+00 at Apron Row A6)




Tracy Municipal Airport - FWD Deflection Data
 Apron Row A8 - (Apron A2)
 (Station 0+00 at Apron Row A6)




Tracy Municipal Airport - FWD Deflection Data
 Apron Row A9 - (Apron A1, A4, and A3)
 (Station 0+00 at Apron Row A6)




Tracy Municipal Airport - FWD Deflection Data
 Apron Row A10 - (Apron A1, A4, and A5)
 (Station 0+00 at South-West end)




Tracy Municipal Airport - FWD Deflection Data
 North Hangar Row H1 - (Hangar Area H1)
 (Station 0+00 at Apron)




Tracy Municipal Airport - FWD Deflection Data
 North Hangar Row H2 - (Hangar Area H1)
 (Station 0+00 at Apron)




Tracy Municipal Airport - FWD Deflection Data
 North Hangar Row H3 - (Hangar Area H1)
 (Station 0+00 at Apron)




Tracy Municipal Airport - FWD Deflection Data
 North Hangar Row H4 - (Hangar Area H2)
 (Station 0+00 at West End)




Tracy Municipal Airport - FWD Deflection Data
 North Hangar Row H5 - (Hangar Area H2)
 (Station 0+00 at West End)




Tracy Municipal Airport - FWD Deflection Data
 North Hangar Row H6 - (Hangar Area H2)
 (Station 0+00 at West End)




Tracy Municipal Airport - FWD Deflection Data
 North Hangar Row H7 - (Hangar Area H2)
 (Station 0+00 at West End)




Tracy Municipal Airport - FWD Deflection Data
 North Hangar Row H8 - (Hangar Area H2)
 (Station 0+00 at North End)




Tracy Municipal Airport - FWD Deflection Data
 Taxiway D (South) - (Hangar Area H3)
 (Station 0+00 at RW 12-30)




Tracy Municipal Airport - FWD Deflection Data
 South Hangar Row B1 - (Hangar Area H3)
 (Station 0+00 at East end)




Tracy Municipal Airport - FWD Deflection Data
 South Hangar Row B2 - (Hangar Area H3)
 (Station 0+00 at East end)



Tracy Municipal Airport - FWD Deflection Data
 South Hangar Row B3 - (Hangar Area H4)
 (Station 0+00 at West end of Taxiway C)




Tracy Municipal Airport - FWD Deflection Data
 South Hangar Row B4 - (Hangar Area H3 and H4)
 (Station 0+00 at Row B3)




Tracy Municipal Airport - FWD Deflection Data
 Road A - Airport Access Road
 (Station 0+00 at South End)


- ◆ Road A - 10 kips
- Road A - 14 kips
- ▲ Road A - 17 kips




Tracy Municipal Airport - FWD Deflection Data
 Road B - Airport Second Access Road
 (Station 0+00 at East End)




Tracy Municipal Airport - FWD Deflection Data
 Road C - FBO Parking Lot
 (Station 0+00 at South End of Parking Lot)



Tracy Municipal Airport - FWD Deflection Data
 Road D - North Apron Access Road (Apron Row A6)
 (Station 0+00 at TW D North)



Tracy Municipal Airport - FWD Deflection Data
 Road E - South Hangar Access Road - Row B5
 (Station 0+00 at Hangar End)



**TRACY MUNICIPAL AIRPORT
PAVEMENT EVALUATION STUDY
PAVEMENT MAINTENANCE/MANAGEMENT PLAN**

**Appendix C
Pavement Condition Survey**

As an aid in determining the performance to date of the existing pavements and to provide a guide for the test program to be conducted in this study a detailed condition survey of all existing pavements was made. This survey consisted of visually observing all pavements and noting deficiencies in areas of distress. A drawing identifying the pavements surveyed is included in this appendix as Plate No. C1. Plate No. C2 gives the stationing control for all segments of pavement included in this report. A drawing indicating the PCI (Pavement Condition Index) rating of each segment of pavement by color is included as Plate No. C3.

The Pavement Condition Survey and Rehabilitation Schedules shown in Tables C1 through C31 include the following information for each pavement segment evaluated, if available:

- F.A.A. Pavement Strength Survey
- F.A.A. Existing Pavement Section, FAA Form 5335
- Date constructed
- Rehabilitation record
- Pavement condition including Pavement Condition Index (PCI)
- Pavement evaluation
- Traffic Index
- Pavement remaining life analysis
- Recommended rehabilitation.

Routine remarking of the pavements is necessary every 8 to 10 years. The scheduled remarking is not shown in Appendix C or Table 4-3 due to space limitations, but it is included in each of the rehabilitation and maintenance projects.

The table of contents of this appendix is shown below:

Plates


Plate No. C1	Pavement Segment Identification
Plate No. C2	Stationing Control Layout Plan
Plate No. C3	Surface Distress – Pavement Condition Index (PCI)

**TRACY MUNICIPAL AIRPORT
PAVEMENT EVALUATION STUDY
PAVEMENT MAINTENANCE/MANAGEMENT PLAN**

**Appendix C
Pavement Condition Survey**

Tables – Pavement Condition Survey and Rehabilitation Schedule

Tables No. C1 through C3	Runway 12-30
Tables No. C4 through C7	Taxiways B & E
Table No. C8	Runway 8-26
Tables No. C9 through C12	Taxiways A & F
Table No. C13	Taxiway D (North)
Table No. C14	Taxiway D (South)
Table No. C15	Taxiway C
Tables No. C16 through C20	Aprons A1-A5 – North Apron Complex
Tables No. C21 through C23	Hangar Area H1 – North Apron Complex
Table No. C24	Hangar Area H2 – North Apron Complex
Table No. C25	Hangar Area H3 – South Apron Complex
Table No. C26	Hangar Area H4 – South Apron Complex
Table No. C27	Road A – Airport Access Road
Table No. C28	Road A – Airport Secondary Access Road
Table No. C29	Road C – FBO Parking Lot
Table No. C30	Road D – North Apron Access Road
Table No. C31	Road E – South Hangar Access Road



LEGEND

C12 SEGMENT OF AIRFIELD REFERRED TO IN THE PAVEMENT CONDITION SURVEY APPENDIX C TABLES C1-C31.

B TRAFFIC INDEX, SEE APPENDIX D

VERIFY SCALES
 BAR IS ONE INCH ON ORIGINAL DRAWING.
 IF NOT ONE INCH ON THIS SHEET, ADJUST SCALES ACCORDINGLY.

Reinard W. Brandley
 CONSULTING AIRPORT ENGINEER
 8125 King Road, Suite 201 • Lodi, California 95650-8804 • (916) 852-4725




NO.	REVISIONS	BY	DATE	ENGINEER OF RECORD


TRACY MUNICIPAL AIRPORT
 CALIFORNIA
PAVEMENT EVALUATION
 PAVEMENT SEGMENT IDENTIFICATION

DESIGN BY: DB
 DRAWN BY: DB
 CHKD BY: RWB
 DATE: MARCH 11, 2013
 CONTRACT No. -
 PROJECT NO: 51.04-13
 DWG FILE: -
 DRAWING SCALE: 1"=200'

SHEET NUMBER
 PLATE No. C1



LEGEND:
 STATION CONTROL (DIRECTION AND STATION VALUE)



VERIFY SCALES
 BAR IS ONE INCH ON ORIGINAL DRAWING.
 IF NOT ONE INCH ON THIS SHEET, ADJUST SCALES ACCORDINGLY.



Reinard W. Brandley
 CONSULTING AIRPORT ENGINEER
 8125 King Road, Suite 201 • Lodi, California 95650-8004 • (916) 652-4725

NO.	REVISIONS	BY	DATE	ENGINEER OF RECORD


TRACY MUNICIPAL AIRPORT
 CALIFORNIA
PAVEMENT EVALUATION
 STATIONING CONTROL LAYOUT PLAN

DESIGN BY: DB
 DRAWN BY: DB
 CHKD BY: RWB
 DATE: MARCH 11, 2013
 CONTRACT NO. -
 PROJECT NO: 51.04-13
 DWG FILE: -
 DRAWING SCALE: 1"=200'

SHEET	NUMBER
PLATE No.	C2



NOTES:
 1. PAVEMENT TESTING & SURVEY PERFORMED OCTOBER 9, 2012



VERIFY SCALES
 BAR IS ONE INCH ON ORIGINAL DRAWING.
 IF NOT ONE INCH ON THIS SHEET, ADJUST SCALES ACCORDINGLY.

Reinard W. Brandley
 CONSULTING AIRPORT ENGINEER
 6125 King Road, Suite 201 • Lodi, California 95650-8004 • (510) 652-4725



NO.	REVISIONS	BY	DATE	ENGINEER OF RECORD

TRACY MUNICIPAL AIRPORT
 CALIFORNIA
PAVEMENT EVALUATION
 SURFACE DISTRESS - PAVEMENT CONDITION INDEX (PCI)

DESIGN BY: DB
 DRAWN BY: DB
 CHKD BY: RWB
 DATE: MARCH 11, 2013
 CONTRACT NO.: -
 PROJECT NO.: 51.04-13
 DWG FILE: -
 DRAWING SCALE: 1"=200'
 SHEET NUMBER
 PLATE No. C3

TABLE No. C1 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE							
Airport:	Tracy Municipal Airport			Date of Survey:	October 9, 2012		
Element:	Runway 12-30						
Station:	0+00 to 14+50						
Dimensions:	1450' x 100'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):				Not Available			
		T-inch	CBR	E ksi	μ	K pci	Remarks
Existing Pavement Section:	PFC						
	PCC						
	AC	6		150	0.35		
	AB	12		40	0.35		
	ASB						
	Subgrade	48		10	0.35		
	Sub-soil	S.I.		25	0.35		
Date Constructed:							
Rehabilitation Record:	Date	Type					
	1980	Heater Remix and 2"-3" AC Overlay					
Pavement Condition:							
Slurry Sealed (moderate ravelling of seal coat)							
Moderate Longitudinal Cracks, Some Transverse Cracking							
9' Paved Shoulder on North Side with transverse cracking, 3' Paved Shoulder on south side.							
Weathering - Moderate		Ravelling - Moderate (seal coat)			Rutting - None		
Pavement Rating = Fair						PCI = 40	
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				A		A1	
FWD Center Plate Deflection - 17 K Load				13-37 (35)		13-37 (35)	
Pavement Structure Remaining Life - Years				182		145	
				FAA - FAARFIELD			
Traffic Index				A		A1	
FWD Center Plate Deflection - 17 K Load				13-37 (35)		13-37 (35)	
Pavement Structure Remaining Life - Years				1998		1556	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2013	B	Rehabilitate Existing Section					
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2028	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Station 0+00 located at south end of Runway 30 proceeding northwest.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C2 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE							
Airport:	Tracy Municipal Airport			Date of Survey:	October 9, 2012		
Element:	Runway 12-30						
Station:	14+50 to 33+00						
Dimensions:	1850' x 100'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):				Not Available			
		T-inch	CBR	E ksi	μ	K pci	Remarks
Existing Pavement Section:	PFC						
	PCC						
	AC	6		150	0.35		
	AB	12		40	0.35		
	ASB						
	Subgrade	48		10	0.35		
	Sub-soil	S.I.		25	0.35		
Date Constructed:							
Rehabilitation Record:		Date	Type				
		1980	Heater Remix and 2"-3" AC Overlay				
Pavement Condition:							
Slurry Sealed (moderate ravelling of seal coat)							
Moderate Longitudinal Cracks, Some Transverse Cracking							
9' Paved Shoulder on North Side with transverse cracking, 3' Paved Shoulder on south side.							
Weathering - Moderate		Ravelling - Moderate (seal coat)			Rutting - None		
Pavement Rating = Fair						PCI = 40	
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				A		A1	
FWD Center Plate Deflection - 17 K Load				17-34 (35)		17-34 (35)	
Pavement Structure Remaining Life - Years				182 - 270		145 - 226	
				FAA - FAARFIELD			
Traffic Index				A		A1	
FWD Center Plate Deflection - 17 K Load				17-34 (35)		17-34 (35)	
Pavement Structure Remaining Life - Years				1998		1556	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2013	B	Rehabilitate Existing Section					
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2028	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Station 0+00 located at south end of Runway 30 proceeding northwest.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C3 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE

Airport:	Tracy Municipal Airport	Date of Survey:	October 9, 2012				
Element:	Runway 12-30						
Station:	33+00 to 40+00						
Dimensions:	700' x 100'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):	Not Available						
Existing Pavement Section:							
	PFC	T-inch	CBR	E ksi	μ	K pci	Remarks
	PCC						
	AC	6		150	0.35		
	AB	12		40	0.35		
	ASB						
	Subgrade	48		10	0.35		
	Sub-soil	S.I.		25	0.35		
Date Constructed:							
Rehabilitation Record:	Date	Type					
	1980	Heater Remix and 2"-3" AC Overlay					
Pavement Condition:							
Slurry Sealed (moderate ravelling of seal coat)							
Moderate Longitudinal Cracks, Some Transverse Cracking							
9' Paved Shoulder on North Side with transverse cracking, 3' Paved Shoulder on south side.							
Weathering - Moderate Ravelling - Moderate (seal coat) Rutting - None							
Pavement Rating = Fair PCI = 40							
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				B		B1	
FWD Center Plate Deflection - 17 K Load				14-36 (35)		14-36 (35)	
Pavement Structure Remaining Life - Years				228 - 225		178 - 176	
				FAA - FAARFIELD			
Traffic Index				B		B1	
FWD Center Plate Deflection - 17 K Load				14-36 (35)		14-36 (35)	
Pavement Structure Remaining Life - Years				2211		1722	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2013	B	Rehabilitate Existing Section					
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2028	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Station 0+00 located at south end of Runway 30 proceeding northwest.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C4 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE							
Airport:	Tracy Municipal Airport				Date of Survey:	October 9, 2012	
Element:	Taxiway BE						
Station:	0+00 to 16+00						
Dimensions:	1600' x 40'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):				Not Available			
		T-inch	CBR	E ksi	μ	K pci	Remarks
Existing Pavement Section:	PFC						
	PCC						
	AC	3.5		350	0.35		
	AB	11		50	0.35		
	ASB						
	Subgrade	48		11	0.35		
	Sub-soil	S.I.		25	0.35		
Date Constructed:							
Rehabilitation Record:	Date	Type					
	1980	Heater Remix and 2"-3" AC Overlay					
Pavement Condition:							
Slurry Sealed (minor ravelling)							
Longitudinal Cracking - Moderate in wheel paths, Transverse Cracking - Very Few							
Weathering - Moderate		Ravelling - Minor (seal coat)			Rutting - Minor		
Pavement Rating = Fair						PCI = 40	
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				C		C1	
FWD Center Plate Deflection - 17 K Load				15-35 (36)		15-35 (36)	
Pavement Structure Remaining Life - Years				105		80	
				FAA - FAARFIELD			
Traffic Index				C		C1	
FWD Center Plate Deflection - 17 K Load				15-35 (36)		15-35 (36)	
Pavement Structure Remaining Life - Years				971		754	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2013	B	Rehabilitate Existing Section					
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2028	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Station 0+00 located at edge of Runway 30 proceeding northwest.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C5 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE

Airport:	Tracy Municipal Airport		Date of Survey:	October 9, 2012			
Element:	Taxiway BE						
Station:	16+00 to 32+00						
Dimensions:	1600' x 40'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):			Not Available				
Existing Pavement Section:							
	PFC						
	PCC						
	AC	3.5		350	0.35		
	AB	11		50	0.35		
	ASB						
	Subgrade	48		11	0.35		
	Sub-soil	S.I.		25	0.35		
Date Constructed:							
Rehabilitation Record:		Date	Type				
		1980	Heater Remix and 2"-3" AC Overlay				
Pavement Condition:							
Slurry Sealed (minor ravelling)							
Longitudinal Cracking - Moderate in wheel paths, Transverse Cracking - Very Few							
Weathering - Moderate Ravelling - Minor (seal coat) Rutting - Minor							
Pavement Rating = Fair							PCI = 40
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				D		D1	
FWD Center Plate Deflection - 17 K Load				17-40 (36)		17-40 (36)	
Pavement Structure Remaining Life - Years				106		82	
				FAA - FAARFIELD			
Traffic Index				D		D1	
FWD Center Plate Deflection - 17 K Load				17-40 (36)		17-40 (36)	
Pavement Structure Remaining Life - Years				1030		800	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2013	B	Rehabilitate Existing Section					
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2028	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Station 0+00 located at edge of Runway 30 proceeding northwest.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C6 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE

Airport:	Tracy Municipal Airport		Date of Survey:	October 9, 2012			
Element:	Taxiway BE						
Station:	32+00 to 40+00						
Dimensions:	800' x 40'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):			Not Available				
Existing Pavement Section:							
	PFC						
	PCC						
	AC	3.5		350	0.35		
	AB	11		50	0.35		
	ASB						
	Subgrade	48		11	0.35		
	Sub-soil	S.I.		25	0.35		
Date Constructed:							
Rehabilitation Record:		Date	Type				
		1980	Heater Remix and 2"-3" AC Overlay				
Pavement Condition:							
Slurry Sealed (minor ravelling)							
Longitudinal Cracking - Moderate in wheel paths, Transverse Cracking - Very Few							
Weathering - Moderate Ravelling - Minor (seal coat) Rutting - Minor							
Pavement Rating = Fair							PCI = 40
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				E		E1	
FWD Center Plate Deflection - 17 K Load				28-37 (36)		28-37 (36)	
Pavement Structure Remaining Life - Years				132		101	
FAA - FAARFIELD							
Traffic Index				E		E1	
FWD Center Plate Deflection - 17 K Load				28-37 (36)		28-37 (36)	
Pavement Structure Remaining Life - Years				1189		928	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2013	B	Rehabilitate Existing Section					
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2028	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Station 0+00 located at edge of Runway 30 proceeding northwest.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C7 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE

Airport:	Tracy Municipal Airport	Date of Survey:	October 9, 2012				
Element:	Taxiway BE						
Station:	40+00 to 43+00						
Dimensions:	300' x 40'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):	Not Available						
Existing Pavement Section:							
	PFC	T-inch	CBR	E ksi	μ	K pci	Remarks
	PCC						
	AC	3.5		150	0.35		
	AB	11		40	0.35		
	ASB						
	Subgrade	48		12	0.35		
	Sub-soil	S.I.		25	0.35		
Date Constructed:							
Rehabilitation Record:	Date	Type					
	1980	Heater Remix and 2"-3" AC Overlay					
Pavement Condition:							
Slurry Sealed (minor ravelling)							
Longitudinal Cracking - Moderate in wheel paths, Transverse Cracking - Very Few							
Weathering - Moderate Ravelling - Minor (seal coat) Rutting - Minor							
Pavement Rating = Poor PCI = 35							
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				E		E1	
FWD Center Plate Deflection - 17 K Load				40-45 (45)		40-45 (45)	
Pavement Structure Remaining Life - Years				116		89	
FAA - FAARFIELD							
Traffic Index				E		E1	
FWD Center Plate Deflection - 17 K Load				40-45 (45)		40-45 (45)	
Pavement Structure Remaining Life - Years				438		340	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2013	B	Rehabilitate Existing Section					
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2028	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Station 0+00 located at edge of Runway 30 proceeding northwest.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C8 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE

Airport:	Tracy Municipal Airport		Date of Survey:	October 9, 2012			
Element:	Runway 8-26						
Station:	0+00 to 40+00						
Dimensions:	4000' x 100'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):			Not Available				
Existing Pavement Section:							
		T-inch	CBR	E ksi	μ	K pci	Remarks
Existing Pavement Section:	PFC						
	PCC						
	AC	6		150	0.35		
	AB	11		30	0.35		
	ASB						
	Subgrade	18		5	0.35		
	Sub-soil	S.I.		15	0.35		
Date Constructed:							
Rehabilitation Record:		Date	Type				
		1977	Heater Remix and 2"-3" AC Overlay				
Pavement Condition:							
Slurry Sealed (moderate ravelling of seal coat), slurry is cracked on existing airfield marking							
Longitudinal Cracking - Moderate, Transverse Cracking - Moderate, Some Block Cracking at edges							
5' Paved Shoulder on North Side, 15' Paved Shoulder on south side with block cracking							
Weathering - Moderate Ravelling - Moderate (seal coat) Rutting - None							
Pavement Rating = Poor PCI = 30							
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				F		F1	
FWD Center Plate Deflection - 17 K Load				21-51 (48)		21-51 (48)	
Pavement Structure Remaining Life - Years				338 - 615		269 - 518	
				FAA - FAARFIELD			
Traffic Index				F		F1	
FWD Center Plate Deflection - 17 K Load				21-51 (48)		21-51 (48)	
Pavement Structure Remaining Life - Years				141 - 9670		115 - 8072	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2015	B	Rehabilitate Existing Section					
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2029	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Station 0+00 located at east end of Runway 26 proceeding west.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C9 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE							
Airport:	Tracy Municipal Airport			Date of Survey:	October 9, 2012		
Element:	Taxiway AF						
Station:	0+00 to 5+00						
Dimensions:	500' x 40'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):				Not Available			
		T-inch	CBR	E ksi	μ	K pci	Remarks
Existing Pavement Section:	PFC						
	PCC						
	AC	6		150	0.35		
	AB	10		40	0.35		
	ASB						
	Subgrade	18		12	0.35		
	Sub-soil	S.I.		15	0.35		
Date Constructed:							
Rehabilitation Record:	Date	Type					
	1977	Heater Remix and 2"-3" AC Overlay					
Pavement Condition:							
Slurry Sealed (moderate ravelling of seal coat)							
Longitudinal Cracking - Minor, Transverse Cracking - Minor							
Weathering - Moderate Ravelling - Moderate (seal coat) Rutting - None							
Pavement Rating = Fair							PCI = 40
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				G		G1	
FWD Center Plate Deflection - 17 K Load				34-44 (38)		34-44 (38)	
Pavement Structure Remaining Life - Years				408		327	
				FAA - FAARFIELD			
Traffic Index				G		G1	
FWD Center Plate Deflection - 17 K Load				34-44 (38)		34-44 (38)	
Pavement Structure Remaining Life - Years				5700		4395	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2015	B	Rehabilitate Existing Section					
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2029	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Station 0+00 located at south edge of Runway 26 proceeding west.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C10 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE

Airport:	Tracy Municipal Airport		Date of Survey:	October 9, 2012		
Element:	Taxiway AF					
Station:	5+00 to 24+00					
Dimensions:	1900' x 40'					
FAA Pavement Strength Survey - Element Identification (Form 5335-1):			Not Available			
Existing Pavement Section:						
	PFC					
	PCC					
	AC	6		150	0.35	
	AB	10		40	0.35	
	ASB					
	Subgrade	18		12	0.35	
	Sub-soil	S.I.		15	0.35	
Date Constructed:						
Rehabilitation Record:	Date	Type				
	1977	Heater Remix and 2"-3" AC Overlay				
Pavement Condition:						
Slurry Sealed (moderate ravelling of seal coat)						
Longitudinal Cracking - Minor, Transverse Cracking - Minor						
Weathering - Moderate Ravelling - Moderate (seal coat) Rutting - None						
Pavement Rating = Poor PCI = 35						
Pavement Remaining Life Analysis			Brandley - Fatigue Analysis			
Traffic Index			H		H1	
FWD Center Plate Deflection - 17 K Load			22-48 (38)		22-48 (38)	
Pavement Structure Remaining Life - Years			342		270	
			FAA - FAARFIELD			
Traffic Index			H		H1	
FWD Center Plate Deflection - 17 K Load			22-48 (38)		22-48 (38)	
Pavement Structure Remaining Life - Years			4598		3583	
Recommended Rehabilitation:						
Date	Rehab. Code	Description				
2015	B	Rehabilitate Existing Section				
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat				
2029	D, E	Crack Repair, Seal Cracks, & Seal Coat				
Remarks:						
Station 0+00 located at south edge of Runway 26 proceeding west.						
FWD used was mean value for section - See FWD Graphs, Appendix B						
For Traffic Index see Appendix D.						

TABLE No. C11 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE

Airport:	Tracy Municipal Airport		Date of Survey:	October 9, 2012			
Element:	Taxiway AF						
Station:	24+00 to 35+00						
Dimensions:	a' x a'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):			Not Available				
Existing Pavement Section:							
	PFC	T-inch	CBR	E ksi	μ	K pci	Remarks
	PCC						
	AC	6		150	0.35		
	AB	10		40	0.35		
	ASB						
	Subgrade	18		12	0.35		
	Sub-soil	S.I.		15	0.35		
Date Constructed:							
Rehabilitation Record:		Date	Type				
		1977	Heater Remix and 2"-3" AC Overlay				
Pavement Condition:							
Slurry Sealed (moderate ravelling of seal coat)							
Longitudinal Cracking - Minor, Transverse Cracking - Minor							
Weathering - Moderate Ravelling - Moderate (seal coat) Rutting - None							
Pavement Rating = Poor PCI = 35							
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				I		I1	
FWD Center Plate Deflection - 17 K Load				30-35 (38)		30-35 (38)	
Pavement Structure Remaining Life - Years				204		163	
				FAA - FAARFIELD			
Traffic Index				I		I1	
FWD Center Plate Deflection - 17 K Load				30-35 (38)		30-35 (38)	
Pavement Structure Remaining Life - Years				3079		2385	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2015	B	Rehabilitate Existing Section					
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2029	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Station 0+00 located at south edge of Runway 26 proceeding west.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C12 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE							
Airport:	Tracy Municipal Airport			Date of Survey:	October 9, 2012		
Element:	Taxiway AF						
Station:	35+00 to 43+00						
Dimensions:	800' x 40'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):				Not Available			
		T-inch	CBR	E ksi	μ	K pci	Remarks
Existing Pavement Section:	PFC						
	PCC						
	AC	6		150	0.35		
	AB	7.5		20	0.35		
	ASB						
	Subgrade	18		9	0.35		
	Sub-soil	S.I.		20	0.35		
Date Constructed:							
Rehabilitation Record:	Date	Type					
	1977	Heater Remix and 2"-3" AC Overlay					
Pavement Condition:							
Slurry Sealed (moderate ravelling of seal coat)							
Longitudinal Cracking - Minor, Transverse Cracking - Minor							
Weathering - Moderate		Ravelling - Moderate (seal coat)			Rutting - None		
Pavement Rating = Poor						PCI = 35	
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				I		I1	
FWD Center Plate Deflection - 17 K Load				38-49 (47)		38-49 (47)	
Pavement Structure Remaining Life - Years				114		88	
				FAA - FAARFIELD			
Traffic Index				I		I1	
FWD Center Plate Deflection - 17 K Load				38-49 (47)		38-49 (47)	
Pavement Structure Remaining Life - Years				99		75	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2015	B	Rehabilitate Existing Section					
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2029	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Station 0+00 located at south edge of Runway 26 proceeding west.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C13 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE

Airport:	Tracy Municipal Airport	Date of Survey:	October 9, 2012																																																		
Element:	Taxiway D (North)																																																				
Station:	0+00 to 1+50																																																				
Dimensions:	150' x 40'																																																				
FAA Pavement Strength Survey - Element Identification (Form 5335-1):	Not Available																																																				
<table border="1"> <thead> <tr> <th></th> <th>T-inch</th> <th>CBR</th> <th>E ksi</th> <th>μ</th> <th>K pci</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td rowspan="7">Existing Pavement Section:</td> <td>PFC</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>PCC</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>AC</td> <td align="center">5.5</td> <td></td> <td align="center">250</td> <td align="center">0.35</td> <td></td> </tr> <tr> <td>AB</td> <td align="center">12.5</td> <td></td> <td align="center">40</td> <td align="center">0.35</td> <td></td> </tr> <tr> <td>ASB</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Subgrade</td> <td align="center">48</td> <td></td> <td align="center">11</td> <td align="center">0.35</td> <td></td> </tr> <tr> <td>Sub-soil</td> <td align="center">S.I.</td> <td></td> <td align="center">25</td> <td align="center">0.35</td> <td></td> </tr> </tbody> </table>					T-inch	CBR	E ksi	μ	K pci	Remarks	Existing Pavement Section:	PFC						PCC						AC	5.5		250	0.35		AB	12.5		40	0.35		ASB						Subgrade	48		11	0.35		Sub-soil	S.I.		25	0.35	
	T-inch	CBR	E ksi	μ	K pci	Remarks																																															
Existing Pavement Section:	PFC																																																				
	PCC																																																				
	AC	5.5		250	0.35																																																
	AB	12.5		40	0.35																																																
	ASB																																																				
	Subgrade	48		11	0.35																																																
	Sub-soil	S.I.		25	0.35																																																
Date Constructed:																																																					
Rehabilitation Record:	Date	Type																																																			
	1977	Heater Remix and 2"-3" AC Overlay																																																			
Pavement Condition:																																																					
Slurry Sealed (moderate ravelling of seal coat)																																																					
Longitudinal Cracking - Moderate, Transverse Cracking - Moderate																																																					
Weathering - Moderate Ravelling - Moderate (seal coat) Rutting - None																																																					
Pavement Rating = Fair			PCI = 40																																																		
Pavement Remaining Life Analysis		Brandley - Fatigue Analysis																																																			
Traffic Index	J	J1																																																			
FWD Center Plate Deflection - 17 K Load	30-37 (32)	30-37 (32)																																																			
Pavement Structure Remaining Life - Years	413	381																																																			
FAA - FAARFIELD																																																					
Traffic Index	J	J1																																																			
FWD Center Plate Deflection - 17 K Load	30-37 (32)	30-37 (32)																																																			
Pavement Structure Remaining Life - Years	Infinite	Infinite																																																			
Recommended Rehabilitation:																																																					
Date	Rehab. Code	Description																																																			
2013	B	Rehabilitate Existing Section																																																			
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat																																																			
2028	D, E	Crack Repair, Seal Cracks, & Seal Coat																																																			
Remarks:																																																					
Station 0+00 located at north edge of Runway 30 proceeding northeast.																																																					
FWD used was mean value for section - See FWD Graphs, Appendix B																																																					
For Traffic Index see Appendix D.																																																					

TABLE No. C14 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE

Airport:	Tracy Municipal Airport	Date of Survey:	October 9, 2012																																																										
Element:	Taxiway D (South)																																																												
Station:	0+00 to 1+50																																																												
Dimensions:	150' x 40'																																																												
FAA Pavement Strength Survey - Element Identification (Form 5335-1):	Not Available																																																												
<table border="1"> <thead> <tr> <th colspan="2"></th> <th>T-inch</th> <th>CBR</th> <th>E ksi</th> <th>μ</th> <th>K pci</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td rowspan="6">Existing Pavement Section:</td> <td>PFC</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>PCC</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>AC</td> <td align="center">3</td> <td></td> <td align="center">250</td> <td align="center">0.35</td> <td></td> <td></td> </tr> <tr> <td>AB</td> <td align="center">7</td> <td></td> <td align="center">35</td> <td align="center">0.35</td> <td></td> <td></td> </tr> <tr> <td>ASB</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Subgrade</td> <td align="center">48</td> <td></td> <td align="center">10</td> <td align="center">0.35</td> <td></td> <td></td> </tr> <tr> <td>Sub-soil</td> <td align="center">S.I.</td> <td></td> <td align="center">25</td> <td align="center">0.35</td> <td></td> <td></td> </tr> </tbody> </table>						T-inch	CBR	E ksi	μ	K pci	Remarks	Existing Pavement Section:	PFC							PCC							AC	3		250	0.35			AB	7		35	0.35			ASB							Subgrade	48		10	0.35			Sub-soil	S.I.		25	0.35		
		T-inch	CBR	E ksi	μ	K pci	Remarks																																																						
Existing Pavement Section:	PFC																																																												
	PCC																																																												
	AC	3		250	0.35																																																								
	AB	7		35	0.35																																																								
	ASB																																																												
	Subgrade	48		10	0.35																																																								
Sub-soil	S.I.		25	0.35																																																									
Date Constructed:	1989																																																												
Rehabilitation Record:	Date	Type																																																											
Pavement Condition:																																																													
Slurry Sealed (moderate ravelling of seal coat)																																																													
Longitudinal Cracking - Moderate, Transverse Cracking - Few Moderate																																																													
Weathering - Moderate Ravelling - Moderate (seal coat) Rutting - None																																																													
Pavement Rating = Poor			PCI = 39																																																										
Pavement Remaining Life Analysis		Brandley - Fatigue Analysis																																																											
Traffic Index		J	J1																																																										
FWD Center Plate Deflection - 17 K Load		52+56 (54)	52+56 (54)																																																										
Pavement Structure Remaining Life - Years		208	191																																																										
		FAA - FAARFIELD																																																											
Traffic Index		J	J1																																																										
FWD Center Plate Deflection - 17 K Load		52+56 (54)	52+56 (54)																																																										
Pavement Structure Remaining Life - Years		Infinite	Infinite																																																										
Recommended Rehabilitation:																																																													
Date	Rehab. Code	Description																																																											
2016	B	Rehabilitate Existing Section																																																											
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat																																																											
2031	D, E	Crack Repair, Seal Cracks, & Seal Coat																																																											
Remarks:																																																													
Station 0+00 located at south edge of Runway 30 proceeding southwest.																																																													
FWD used was mean value for section - See FWD Graphs, Appendix B																																																													
For Traffic Index see Appendix D.																																																													

TABLE No. C15 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE							
Airport:	Tracy Municipal Airport				Date of Survey:	October 9, 2012	
Element:	Taxiway C						
Station:	0+00 to 14+00						
Dimensions:	1400' x 40'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):				Not Available			
		T-inch	CBR	E ksi	μ	K pci	Remarks
Existing Pavement Section:	PFC						
	PCC						
	AC	2		250	0.35		
	AB	8		45	0.35		
	ASB						
	Subgrade	48		11	0.35		
	Sub-soil	S.I.		25	0.35		
Date Constructed:							
Rehabilitation Record:	Date	Type					
Pavement Condition:							
No seal coat.							
Longitudinal Cracking - Some moderate cracking at edges, crack sealed.							
Weathering - Moderate Ravelling - None Rutting - None							
Pavement Rating = Fair						PCI = 40	
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				J		J1	
FWD Center Plate Deflection - 17 K Load				28-53 (53)		28-53 (53)	
Pavement Structure Remaining Life - Years				232 - 406		214 - 375	
				FAA - FAARFIELD			
Traffic Index				J		J1	
FWD Center Plate Deflection - 17 K Load				28-53 (53)		28-53 (53)	
Pavement Structure Remaining Life - Years				Infinite		Infinite	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2016	B	Rehabilitate Existing Section					
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2031	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Station 0+00 located at south edge of Runway 30 proceeding southwest.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C16 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE

Airport:	Tracy Municipal Airport		Date of Survey:	October 9, 2012			
Element:	Apron A1						
Station:	83/85 Overlay						
Dimensions:	490' x 305'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):			Not Available				
Existing Pavement Section:							
	PFC	T-inch	CBR	E ksi	μ	K pci	Remarks
	PCC						
	AC	5.5		250	0.35		
	AB	6		50	0.35		
	ASB						
	Subgrade	48		13	0.35		
	Sub-soil	S.I.		25	0.35		
Date Constructed:							
Rehabilitation Record:		Date	Type				
		1983/1985	1"-3" AC Overlay				
Pavement Condition:							
No seal coat.							
Longitudinal and Transverse Cracking - Moderate to Severe, Sealed, mostly at paving joints some at edge of apron.							
Weathering - Moderate Ravelling - Minor Rutting - None							
Pavement Rating = Poor						PCI = 35	
Pavement Remaining Life Analysis			Brandley - Fatigue Analysis				
Traffic Index			K		K1		
FWD Center Plate Deflection - 17 K Load			25-30 (30)		25-30 (30)		
Pavement Structure Remaining Life - Years			77 - 163		58 - 126		
			FAA - FAARFIELD				
Traffic Index			K		K1		
FWD Center Plate Deflection - 17 K Load			25-30 (30)		25-30 (30)		
Pavement Structure Remaining Life - Years			361 - 15600		279 - 12185		
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2014	A	Remove and Reconstruct Existing Section					
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2030	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Stationing as shown in Appendix B.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C17 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE

Airport:	Tracy Municipal Airport		Date of Survey:	October 9, 2012			
Element:	Apron A2						
Station:	83/85 Reconstruct						
Dimensions:	770' x 500'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):			Not Available				
Existing Pavement Section:							
	PFC	T-inch	CBR	E ksi	μ	K pci	Remarks
	PCC						
	AC	2		250	0.35		
	AB	5		35	0.35		
	ASB	4.5		20	0.35		
	Subgrade	48		6	0.35		
	Sub-soil	S.I.		25	0.35		
Date Constructed:							
Rehabilitation Record:		Date	Type				
		1983/1985	Pavement Section Reconstruction				
Pavement Condition:							
No seal coat.							
Longitudinal and Transverse Cracking - Moderate to Severe, Sealed, mostly at paving joints some at edge of apron.							
Weathering - Moderate		Ravelling - Minor		Rutting - None			
Pavement Rating = Poor						PCI = 35	
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				K		K1	
FWD Center Plate Deflection - 17 K Load				40-78 (78)		40-78 (78)	
Pavement Structure Remaining Life - Years				18 - 130		13 - 99	
				FAA - FAARFIELD			
Traffic Index				K		K1	
FWD Center Plate Deflection - 17 K Load				40-78 (78)		40-78 (78)	
Pavement Structure Remaining Life - Years				1 - 2600		0 - 2025	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2014	A	Remove and Reconstruct Existing Section					
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2030	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Stationing as shown in Appendix B.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C18 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE

Airport:	Tracy Municipal Airport		Date of Survey:	October 9, 2012			
Element:	Apron A3						
Station:	1999 Reconstruct						
Dimensions:	170' x 220'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):			Not Available				
Date Constructed:							
Rehabilitation Record:		Date	Type				
		1999	Pavement Section Reconstruction				
Pavement Condition:							
No Seal Coat							
Cracking - Some moderate block cracking							
Weathering - Moderate Ravelling - Minor Rutting - None							
Pavement Rating = Poor							PCI = 38
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				K		K1	
FWD Center Plate Deflection - 17 K Load				30-69 (69)		30-69 (69)	
Pavement Structure Remaining Life - Years				16		11	
				FAA - FAARFIELD			
Traffic Index				K		K1	
FWD Center Plate Deflection - 17 K Load				30-69 (69)		30-69 (69)	
Pavement Structure Remaining Life - Years				4		2	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2014	A	Remove and Reconstruct Existing Section					
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2030	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Stationing as shown in Appendix B.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C19 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE

Airport:	Tracy Municipal Airport	Date of Survey:	October 9, 2012				
Element:	Apron A4						
Station:	Old North Apron (South Portion)						
Dimensions:	300' x 350'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):	Not Available						
Existing Pavement Section:							
	PFC	T-inch	CBR	E ksi	μ	K pci	Remarks
	PCC						
	AC	2		250	0.35		
	AB	4		60	0.35		
	ASB						
	Subgrade	48		7	0.35		
	Sub-soil	S.I.		25	0.35		
Date Constructed:							
Rehabilitation Record:	Date	Type					
Pavement Condition:							
Slurry Sealed (moderate ravelling of seal coat)							
Longitudinal and Transverse Cracking - Moderate to Severe, Sealed, mostly at paving joints, Some moderate block cracking.							
Weathering - Moderate Ravelling - Minor Rutting - None							
Pavement Rating = Poor PCI = 39							
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				K		K1	
FWD Center Plate Deflection - 17 K Load				45-85 (80)		45-85 (80)	
Pavement Structure Remaining Life - Years				2		2	
				FAA - FAARFIELD			
Traffic Index				K		K1	
FWD Center Plate Deflection - 17 K Load				45-85 (80)		45-85 (80)	
Pavement Structure Remaining Life - Years				0		0	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2014	A	Remove and Reconstruct Existing Section					
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2030	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Stationing as shown in Appendix B.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C20 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE

Airport:	Tracy Municipal Airport	Date of Survey:	October 9, 2012				
Element:	Apron A5						
Station:	Old North Apron (North Portion)						
Dimensions:	300' x 230'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):	Not Available						
Existing Pavement Section:							
	PFC	T-inch	CBR	E ksi	μ	K pci	Remarks
	PCC						
	AC	2		250	0.35		
	AB	4		60	0.35		
	ASB						
	Subgrade	48		7	0.35		
	Sub-soil	S.I.		25	0.35		
Date Constructed:							
Rehabilitation Record:	Date	Type					
Pavement Condition:							
Slurry Sealed (moderate ravelling of seal coat)							
Longitudinal and Transverse Cracking - Moderate to Severe, Sealed,							
Some moderate to severe block cracking.							
Weathering - Moderate		Ravelling - Moderate (seal coat)			Rutting - None		
Pavement Rating = Poor						PCI = 39	
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				L		L1	
FWD Center Plate Deflection - 17 K Load				45-80 (80)		45-80 (80)	
Pavement Structure Remaining Life - Years				10		7	
				FAA - FAARFIELD			
Traffic Index				L		L1	
FWD Center Plate Deflection - 17 K Load				45-80 (80)		45-80 (80)	
Pavement Structure Remaining Life - Years				0		0	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2014	A	Remove and Reconstruct Existing Section					
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2030	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Stationing as shown in Appendix B.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C21 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE

Airport:	Tracy Municipal Airport	Date of Survey:	October 9, 2012
Element:	Hangar Area H1		
Station:	North Hangars	Row	H1
Dimensions:	160' x 50'		
FAA Pavement Strength Survey - Element Identification (Form 5335-1):	Not Available		

		T-inch	CBR	E ksi	μ	K pci	Remarks
Existing Pavement Section:	PFC						
	PCC						
	AC	2		250	0.35		
	AB	4		50	0.35		
	ASB						
	Subgrade	48		20	0.35		
	Sub-soil	S.I.		25	0.35		

Date Constructed: 1975

Rehabilitation Record:	Date	Type

Pavement Condition:

Severe Weathering - No seal coat.

Longitudinal and Transverse Cracking - Moderate to Severe

Weathering - Severe Ravelling - None Rutting - None

Pavement Rating = Poor PCI = 39

Pavement Remaining Life Analysis	Brandley - Fatigue Analysis	
Traffic Index	N	N1
FWD Center Plate Deflection - 10 K Load	22-27 (27)	22-27 (27)
Pavement Structure Remaining Life - Years	321	289

FAA - FAARFIELD		
Traffic Index	N	N1
FWD Center Plate Deflection - 10 K Load	22-27 (27)	22-27 (27)
Pavement Structure Remaining Life - Years	Infinite	Infinite

Recommended Rehabilitation:

Date	Rehab. Code	Description
2014	A	Remove and Reconstruct Existing Section
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat
2031	D, E	Crack Repair, Seal Cracks, & Seal Coat

Remarks: Stationing as shown in Appendix B.

FWD used was mean value for section - See FWD Graphs, Appendix B

For Traffic Index see Appendix D.

TABLE No. C22 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE

Airport:	Tracy Municipal Airport	Date of Survey:	October 9, 2012				
Element:	Hangar Area H1						
Station:	North Hangars	Row H2					
Dimensions:	160' x 70'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):	Not Available						
Existing Pavement Section:							
	PFC	T-inch	CBR	E ksi	μ	K pci	Remarks
	PCC						
	AC	2		150	0.35		
	AB	4		20	0.35		
	ASB						
	Subgrade	48		5	0.35		
	Sub-soil	S.I.		25	0.35		
Date Constructed:	1975						
Rehabilitation Record:	Date	Type					
Pavement Condition:							
Severe Weathering - No seal coat on Row H3. Row H2 has a seal coat (ravelling)							
Longitudinal and Transverse Cracking - Moderate to Severe							
Light Block Cracking on Row H2. Large Patched Area on Row H3							
Weathering - Severe Ravelling - Moderate Rutting - None							
Pavement Rating = Fair			PCI = 44				
Pavement Remaining Life Analysis		Brandley - Fatigue Analysis					
Traffic Index	N	N1					
FWD Center Plate Deflection - 10 K Load	73-90 (80)	73-90 (80)					
Pavement Structure Remaining Life - Years	27	24					
FAA - FAARFIELD							
Traffic Index	N	N1					
FWD Center Plate Deflection - 10 K Load	73-90 (80)	73-90 (80)					
Pavement Structure Remaining Life - Years	93	82					
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2014	A	Remove and Reconstruct Existing Section					
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2031	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Stationing as shown in Appendix B.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C23 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE							
Airport:	Tracy Municipal Airport			Date of Survey:	October 9, 2012		
Element:	Hangar Area H1						
Station:	North Hangars Row H3						
Dimensions:	160' x 40'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):				Not Available			
		T-inch	CBR	E ksi	μ	K pci	Remarks
Existing Pavement Section:	PFC						
	PCC						
	AC	2		250	0.35		
	AB	4		50	0.35		
	ASB						
	Subgrade	48		10	0.35		
	Sub-soil	S.I.		25	0.35		
Date Constructed:		1975					
Rehabilitation Record:	Date	Type					
Pavement Condition:							
Severe Weathering - No seal coat.							
Longitudinal and Transverse Cracking - Severe							
Large Patched Area							
Weathering - Severe Ravelling - Moderate Rutting - None							
Pavement Rating = Very Poor PCI = 24							
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				N		N1	
FWD Center Plate Deflection - 10 K Load				32-45 (40)		32-45 (40)	
Pavement Structure Remaining Life - Years				132		117	
				FAA - FAARFIELD			
Traffic Index				N		N1	
FWD Center Plate Deflection - 10 K Load				32-45 (40)		32-45 (40)	
Pavement Structure Remaining Life - Years				Infinite		Infinite	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2014	A	Remove and Reconstruct Existing Section					
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2031	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks: Stationing as shown in Appendix B.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C24 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE

Airport:	Tracy Municipal Airport		Date of Survey:	October 9, 2012			
Element:	Hangar Area H2						
Station:	North Hangars Future Rows H4 to H8						
Dimensions:	72,000 square feet						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):			Not Available				
		T-inch	CBR	E ksi	μ	K pci	Remarks
Existing Pavement Section:	PFC						
	PCC						
	AC	2		250	0.35		
	AB	5		35	0.35		
	ASB	4.5		20	0.35		
	Subgrade	48		6	0.35		
	Sub-soil	S.I.		25	0.35		
Date Constructed:		1985					
Rehabilitation Record:	Date	Type					
Pavement Condition:							
Moderate Weathering - No seal coat.							
Longitudinal Cracks - Moderate cracking, mostly along taxiway edges Transverse Cracks - Very Few Cracks are Sealed.							
Weathering - Moderate		Ravelling - None		Rutting - None			
Pavement Rating = Fair						PCI = 40	
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				J		J1	
FWD Center Plate Deflection - 17 K Load				26-80 (78)		26-80 (78)	
Pavement Structure Remaining Life - Years				138 - 413		127 - 381	
				FAA - FAARFIELD			
Traffic Index				J		J1	
FWD Center Plate Deflection - 17 K Load				26-80 (78)		26-80 (78)	
Pavement Structure Remaining Life - Years				Infinite		Infinite	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2015	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2022	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2029	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Stationing as shown in Appendix B.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C25 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE							
Airport:	Tracy Municipal Airport				Date of Survey:	October 9, 2012	
Element:	Hangar Area H3						
Station:	Taxilanes for Existing South Hangars						
Dimensions:	300,000 square feet						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):				Not Available			
		T-inch	CBR	E ksi	μ	K pci	Remarks
Existing Pavement Section:	PFC						
	PCC						
	AC	3		250	0.35		
	AB	7		25	0.35		
	ASB						
	Subgrade	48		10	0.35		
	Sub-soil	S.I.		25	0.35		
Date Constructed:							
Rehabilitation Record:		Date	Type				
Pavement Condition:							
Slurry Sealed (moderate ravelling of seal coat)							
Longitudinal Cracks - Moderate, Transverse Cracks - Moderate,							
Block Cracking - Moderate in front of hangars, Slight Rutting between hangars.							
Weathering - Moderate Ravelling - Moderate (seal coat) Rutting - None							
Pavement Rating = Poor						PCI = 32	
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				M		M1	
FWD Center Plate Deflection - 17 K Load				35-65 (61)		35-65 (61)	
Pavement Structure Remaining Life - Years				76 - 177		69 - 163	
				FAA - FAARFIELD			
Traffic Index				M		M1	
FWD Center Plate Deflection - 17 K Load				35-65 (61)		35-65 (61)	
Pavement Structure Remaining Life - Years				Infinite		Infinite	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2016	A	Remove and Reconstruct Existing Section					
2023	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2031	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Stationing as shown in Appendix B.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C26 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE

Airport:	Tracy Municipal Airport		Date of Survey:	October 9, 2012			
Element:	Hangar Area H4						
Station:	Taxilane for Future South Development						
Dimensions:	41,000 square feet						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):			Not Available				
		T-inch	CBR	E ksi	μ	K pci	Remarks
Existing Pavement Section:	PFC						
	PCC						
	AC	2		250	0.35		
	AB	5		60	0.35		
	ASB	5		35	0.35		
	Subgrade	48		15	0.35		
	Sub-soil	S.I.		25	0.35		
Date Constructed:							
Rehabilitation Record:		Date	Type				
Pavement Condition:							
Moderate Weathering - No Seal Coat							
Longitudinal Cracks - Light, Few along edge of taxiway, Transverse Cracks - None							
Weathering - Moderate Ravelling - None Rutting - None							
Pavement Rating = Fair							PCI = 40
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				M		M1	
FWD Center Plate Deflection - 17 K Load				34-46 (42)		34-46 (42)	
Pavement Structure Remaining Life - Years				194 - 196		178 - 179	
				FAA - FAARFIELD			
Traffic Index				M		M1	
FWD Center Plate Deflection - 17 K Load				34-46 (42)		34-46 (42)	
Pavement Structure Remaining Life - Years				Infinite		Infinite	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2015	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2022	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2029	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Stationing as shown in Appendix B.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C27 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE							
Airport:	Tracy Municipal Airport				Date of Survey:	October 9, 2012	
Element:	Road A - Airport Access Road						
Station:	0+00 to 14+00						
Dimensions:	1400' x 60'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):				Not Available			
		T-inch	CBR	E ksi	μ	K pci	Remarks
Existing Pavement Section:	PFC						
	PCC						
	AC	-		-	0.35		
	AB	-		-	0.35		
	ASB	0		0	0.35		
	Subgrade	-		-	0.35		
	Sub-soil	S.I.		-	0.35		
Date Constructed:							
Rehabilitation Record:		Date	Type				
Pavement Condition:							
Station 0-200 - No Slurry Seal, Station 200-1400 - Slurry Sealed							
Longitudinal Cracks - Moderate, Transverse Cracks - Moderate							
Weathering - Moderate Ravelling - Light Rutting - None							
Pavement Rating = Fair						PCI = 40	
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				-		-1	
FWD Center Plate Deflection - 17 K Load				33-95 (95)		33-95 (95)	
Pavement Structure Remaining Life - Years				-		-	
				FAA - FAARFIELD			
Traffic Index				-		-1	
FWD Center Plate Deflection - 17 K Load				33-95 (95)		33-95 (95)	
Pavement Structure Remaining Life - Years				-		-	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2015	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2022	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2029	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Stationing as shown in Appendix B.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C28 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE							
Airport:	Tracy Municipal Airport			Date of Survey:	October 9, 2012		
Element:	Road B - Airport Secondary Access Road						
Station:	0+00 to 1+20						
Dimensions:	120' x 30'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):				Not Available			
		T-inch	CBR	E ksi	μ	K pci	Remarks
Existing Pavement Section:	PFC						
	PCC						
	AC	2		250	0.35		
	AB	5		80	0.35		
	ASB	5		55	0.35		
	Subgrade	48		13	0.35		
	Sub-soil	S.I.		25	0.35		
Date Constructed:		1985					
Rehabilitation Record:	Date	Type					
Pavement Condition:							
Slurry Sealed, Moderate Weathering							
No Cracking							
Weathering - Moderate Ravelling - Light Rutting - None							
Pavement Rating = Fair							PCI = 45
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				0		01	
FWD Center Plate Deflection - 17 K Load				30-38 (38)		30-38 (38)	
Pavement Structure Remaining Life - Years				39		34	
				FAA - FAARFIELD			
Traffic Index				0		01	
FWD Center Plate Deflection - 17 K Load				30-38 (38)		30-38 (38)	
Pavement Structure Remaining Life - Years				6256		5708	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2015	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2022	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2029	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Stationing as shown in Appendix B.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C29 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE							
Airport:	Tracy Municipal Airport				Date of Survey:	October 9, 2012	
Element:	Road C - FBO Parking Lot						
Station:	0+00 to 3+70						
Dimensions:	370' x 80'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):				Not Available			
		T-inch	CBR	E ksi	μ	K pci	Remarks
Existing Pavement Section:	PFC						
	PCC						
	AC	-		-	0.35		
	AB	-		-	0.35		
	ASB	0		0	0.35		
	Subgrade	-		-	0.35		
	Sub-soil	S.I.		-	0.35		
Date Constructed:							
Rehabilitation Record:		Date	Type				
Pavement Condition:							
Parking Lot. Station 0-290 - No Slurry Seal, Station 290-370 - Slurry Sealed							
Longitudinal Cracks - None, Transverse Cracks - None							
Weathering - Moderate		Ravelling - Light		Rutting - None			
Pavement Rating = Fair						PCI = 45	
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				-		-1	
FWD Center Plate Deflection - 17 K Load				26-61 (38)		26-61 (38)	
Pavement Structure Remaining Life - Years				-		-	
				FAA - FAARFIELD			
Traffic Index				-		-1	
FWD Center Plate Deflection - 17 K Load				26-61 (38)		26-61 (38)	
Pavement Structure Remaining Life - Years				-		-	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2015	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2022	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2029	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Stationing as shown in Appendix B.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C30 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE

Airport:	Tracy Municipal Airport	Date of Survey:	October 9, 2012				
Element:	Road D - North Apron Access Road						
Station:	6+20 to 7+20						
Dimensions:	100' x 30'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):	Not Available						
Existing Pavement Section:							
	PFC	T-inch	CBR	E ksi	μ	K pci	Remarks
	PCC						
	AC	2		250	0.35		
	AB	5		90	0.35		
	ASB	5		60	0.35		
	Subgrade	48		23	0.35		
	Sub-soil	S.I.		25	0.35		
Date Constructed:	1985						
Rehabilitation Record:	Date	Type					
Pavement Condition:							
No seal coat.							
Longitudinal and Transverse Cracking - Moderate to Severe, Sealed							
Weathering - Moderate Ravelling - Moderate Rutting - None							
Pavement Rating = Poor			PCI = 35				
Pavement Remaining Life Analysis		Brandley - Fatigue Analysis					
Traffic Index	0	01					
FWD Center Plate Deflection - 17 K Load	18-28 (28)	18-28 (28)					
Pavement Structure Remaining Life - Years	65	57					
FAA - FAARFIELD							
Traffic Index	0	01					
FWD Center Plate Deflection - 17 K Load	18-28 (28)	18-28 (28)					
Pavement Structure Remaining Life - Years	83000	75000					
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2015	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2022	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2029	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Stationing as shown in Appendix B.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

TABLE No. C31 - PAVEMENT CONDITION SURVEY AND REHABILITATION SCHEDULE

Airport:	Tracy Municipal Airport		Date of Survey:	October 9, 2012			
Element:	Road E - South Hangar Access Road						
Station:	0+00 to 14+00						
Dimensions:	1400' x 35'						
FAA Pavement Strength Survey - Element Identification (Form 5335-1):			Not Available				
		T-inch	CBR	E ksi	μ	K pci	Remarks
Existing Pavement Section:	PFC						
	PCC						
	AC	2.5		250	0.35		
	AB	6		30	0.35		
	ASB	0		0	0.35		
	Subgrade	48		13	0.35		
	Sub-soil	S.I.		25	0.35		
Date Constructed:		1989					
Rehabilitation Record:	Date	Type					
Pavement Condition:							
Moderate Weathering - No Seal Coat							
Longitudinal Cracks - Moderate 3'-4' from edge of road, Transverse Cracks - Some light cracking							
Weathering - Moderate		Ravelling - Moderate		Rutting - None			
Pavement Rating = Poor						PCI = 37	
Pavement Remaining Life Analysis				Brandley - Fatigue Analysis			
Traffic Index				0		01	
FWD Center Plate Deflection - 17 K Load				26-85 (58)		26-85 (58)	
Pavement Structure Remaining Life - Years				3 - 12		2 - 12	
				FAA - FAARFIELD			
Traffic Index				0		01	
FWD Center Plate Deflection - 17 K Load				26-85 (58)		26-85 (58)	
Pavement Structure Remaining Life - Years				4 - 59		3 - 52	
Recommended Rehabilitation:							
Date	Rehab. Code	Description					
2015	D, E	Crack Repair, Seal Cracks, & Seal Coat					
2021	B	Rehabilitate Existing Section					
2031	D, E	Crack Repair, Seal Cracks, & Seal Coat					
Remarks:							
Stationing as shown in Appendix B.							
FWD used was mean value for section - See FWD Graphs, Appendix B							
For Traffic Index see Appendix D.							

**TRACY MUNICIPAL AIRPORT
PAVEMENT EVALUATION STUDY
PAVEMENT MAINTENANCE/MANAGEMENT PLAN**

**Appendix D
Traffic Summary**

This Appendix summarizes the design characteristics of all the aircraft that are currently utilizing the airport. It also provides existing aircraft operations by type, as well as the number of annual operations currently operating at the airport.

The total annual operations of each aircraft group for each area have been calculated as "Traffic Indexes" and are included in Table No. D2. The traffic for each Traffic Index is the traffic that was used to calculate deep-seated distresses in the pavement sections and to calculate the predicted remaining life of each pavement section.

The Fixed Base Operator (FBO) at the airport feels there is a potential for additional hangar development that he believes will attract an increased amount of general aviation aircraft as well as more jet aircraft to the Tracy Municipal Airport. The traffic indexes used in this analysis were based on existing traffic and likely potential increases in traffic. The FBO has a much more optimistic view of the amount of forecast traffic that his new hangar development could generate. Since the number of operations for the optimistic forecast is significantly different than the likely forecast traffic, some enhanced traffic indexes were created and used for additional analysis. The additional analysis has been provided for use if this future optimistic traffic forecast is realized. In order to evaluate the effects that additional traffic would have, a new set of traffic indexes were prepared and used in the Fatigue Analysis studies. These new enhanced traffic indexes utilize the optimistic forecasts that have higher operations of the single engine aircraft and all jet aircraft. The new enhanced traffic indexes have also been included in Table No. D3. The traffic index designation is the same as with the existing forecasts except that a "1" has been added to the Index. For example, traffic index "A" is the likely forecast of traffic and "A1" is the optimistic forecast of traffic. The Fatigue Analysis and FAARFIELD analysis was conducted using both the forecast traffic indexes and the enhanced traffic indexes.

A table of contents of this appendix is shown below:

Plates:



Plate No. D1	Traffic Distribution – Traffic Index
--------------	--------------------------------------

Tables

Table No. D1	Summary of Traffic Data for Tracy Municipal Airport
--------------	---

Table No. D2	Summary of Traffic Indexes (Likely Forecast)
--------------	--

Table No. D3	Summary of Enhanced Traffic Indexes (Optimistic Forecast)
--------------	---



VERIFY SCALES
 BAR IS ONE INCH ON ORIGINAL DRAWING.
 IF NOT ONE INCH ON THIS SHEET, ADJUST SCALES ACCORDINGLY.

LEGEND
B TRAFFIC INDEX, SEE APPENDIX D
 X

Reinard W. Brandley
 CONSULTING AIRPORT ENGINEER
 8125 King Road, Suite 201
 Lodi, California 95650-8004
 (916) 852-4725



NO.	REVISIONS	BY	DATE	ENGINEER OF RECORD

TRACY MUNICIPAL AIRPORT
 CALIFORNIA
PAVEMENT EVALUATION
 TRAFFIC DISTRIBUTION - TRAFFIC INDEX

DESIGN BY: DB
 DRAWN BY: DB
 CHKD BY: RWB
 DATE: MARCH 11, 2013
 CONTRACT No. -
 PROJECT NO: 51.04-13
 DWG FILE: -
 DRAWING SCALE: 1"=200'
 SHEET NUMBER
 PLATE No. D1

APPENDIX D - TRAFFIC SUMMARY

TABLE No. D1 - Summary of Traffic Data for Tracy Municipal Airport

Aircraft Group	Aircraft Type	Aircraft MTOW (lbs)	Gear Configuration	2012 Annual Operations	2012 Daily Operations
1	Single Engine	3,000	Single	61,000	167
2	Twin Engine	4,000	Single	5,000	14
3	Jet Aircraft 15k	15,000	Dual	2,400	7
4	Jet Aircraft 30k	30,000	Dual	600	2
5	Automobile	4,000	Single	72,000	197
6	H-20 Truck	18,000/Axle	Dual	730	2
Total 2012 Aircraft Operations				69,000	189
Total 2012 Vehicle Operations				72,730	199

TABLE No. D2 - Summary of Traffic Indexes (Likely Forecast)

Aircraft Group	Traffic Index (Aircraft Operations in 2012)														
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O
1	48,800	13,664	7,534	28,304	8,479	12,200	6,100	6,009	22,021	29,402	7,412	3,081	48,800	3,000	-
2	4,000	1,480	1,808	2,045	785	1,000	500	218	1,715	620	3,283	528	1,000	-	-
3	2,160	1,771	1,177	1,042	821	240	120	176	379	-	2,219	181	-	-	-
4	540	443	294	262	197	60	30	46	103	-	557	44	-	-	-
5	-	-	-	-	-	-	-	-	-	-	-	-	-	-	72,000
6	-	-	-	-	-	-	-	-	-	-	-	-	-	-	730
Total 2012 Operations	55,500	17,358	10,813	31,653	10,282	13,500	6,750	6,448	24,218	30,022	13,469	3,833			

Aircraft Group	Traffic Index Growth Rates (Calculated Average Annual Growth Rate)														
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O
1	1.06%	1.06%	1.06%	1.06%	1.06%	1.06%	1.06%	1.06%	1.06%	1.06%	1.06%	1.06%	1.06%	1.06%	-
2	1.94%	1.94%	1.94%	1.94%	1.94%	1.94%	1.94%	1.94%	1.94%	1.94%	1.94%	1.94%	1.94%	-	-
3	3.50%	3.50%	3.50%	3.50%	3.50%	3.50%	3.50%	3.50%	3.50%	3.50%	-	3.50%	3.50%	-	-
4	3.50%	3.50%	3.50%	3.50%	3.50%	3.50%	3.50%	3.50%	3.50%	-	3.50%	3.50%	-	-	-
5	-	-	-	-	-	-	-	-	-	-	-	-	-	-	2.00%
6	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3.00%

TABLE No. D3 - Summary of Enhanced Traffic Indexes (Optimistic Forecast)

Aircraft Group	Traffic Index (Aircraft Operations in 2012)														
	A1	B1	C1	D1	E1	F1	G1	H1	I1	J1	K1	L1	M1	N1	O1
1	55,200	15,456	8,522	32,016	9,591	13,800	6,900	6,797	24,909	33,258	8,384	3,485	55,200	3,500	-
2	4,000	1,480	1,808	2,045	785	1,000	500	218	1,715	620	3,283	528	1,000	-	-
3	3,096	2,539	1,687	1,493	1,176	344	172	253	544	-	3,180	260	-	-	-
4	774	635	422	376	283	86	43	66	147	-	798	62	-	-	-
5	-	-	-	-	-	-	-	-	-	-	-	-	-	-	86,400
6	-	-	-	-	-	-	-	-	-	-	-	-	-	-	876
Total 2012 Operations	63,070	20,109	12,438	35,930	11,835	15,230	7,615	7,333	27,315	33,878	15,644	4,334	56,200		

Aircraft Group	Traffic Index Growth Rates (Calculated Average Annual Growth Rate)														
	A1	B1	C1	D1	E1	F1	G1	H1	I1	J1	K1	L1	M1	N1	O1
1	1.09%	1.09%	1.09%	1.09%	1.09%	1.09%	1.09%	1.09%	1.09%	1.09%	1.09%	1.09%	1.09%	1.09%	-
2	1.94%	1.94%	1.94%	1.94%	1.94%	1.94%	1.94%	1.94%	1.94%	1.94%	1.94%	1.94%	1.94%	-	-
3	4.01%	4.01%	4.01%	4.01%	4.01%	4.01%	4.01%	4.01%	4.01%	-	4.01%	4.01%	-	-	-
4	4.01%	4.01%	4.01%	4.01%	4.01%	4.01%	4.01%	4.01%	4.01%	-	4.01%	4.01%	-	-	-
5	-	-	-	-	-	-	-	-	-	-	-	-	-	-	2.00%
6	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3.00%